

New York State Department of Transportation

PIA Safety Flag NB23CTW001

By: Rehan Afridi

Flag Date: May 30, 2023

Superseding Information:

No Flags Superseded

Structure Information

BIN: 1065318

Feature Carried: 278I278IX2M23027

Feature Crossed: 6TH AVENUE

Orientation: 8 - NORTHWEST

Region: 11 - NEW YORK CITY

County: KINGS

Political Unit: City of NEW YORK

Approximate Year Built: 1962

Posted Load Matches Inventory : Yes

Bridge Load Posting (Tons) : Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp

Number of Spans: 322

Verbal Notification Information

Person Notified: Muhammad Mubeen

Date: May 30, 2023 11:45:00 AM

Of: NYSDOT Region 11

Signature Information

Signature: Rehan Afridi, P.E. 075185

Date: May 31, 2023

Reviewed By: Robert Kemp

Date: May 31, 2023

Attachments: 5

Flagged Elements**No Flagged Elements*****Flagged Condition Description***


This PIA Safety Flag No. NB23CTW001 is a New Flag.

Location: Span 83, Pier 83, Column C1 at base.

The electrical conduit attached at the begin face of Column C1 is broken (no junction box). There are exposed live wires at the conduit end near the base of the column. The subject location is at the intersection of 55th Street and westbound 3rd Avenue service road, adjacent to a pedestrian walk and is accessible by the public.

The inspection team temporarily secured the location using caution tape. However, this condition warrants a PIA Safety Flag.

The flagged location can be accessed from westbound 3rd Avenue or the service road.

Flag PhotographsPhoto Number: **1**Photo Filename: **Location Plan.jpg**

LOCATION OF PIA
SAFETY FLAG
NB23CTW001

Attachment Description: Flag Location Plan

Photo Number: 2

Photo Filename: IMG_1573.JPG



Attachment Description: General View of Column C1 at Pier 83. Looking End. (For specific Flag Location at Column C1 base, see Photo Nos. 3 and 4 that follow).

Photo Number: 3

Photo Filename: IMG_1574.JPG



Attachment Description: General view of broken electrical conduit at column base with exposed live wires. Looking End.

Photo Number: 4

Photo Filename: IMG_1575.JPG



Attachment Description: Close up view of broken electrical conduit at column base with exposed live wires.
Looking End.

Photo Number: 5

Photo Filename: IMG_1578.JPG



Attachment Description: Flagged location temporarily secured by the inspection team. Looking End